



基礎の縦割れを補修





基礎の縦割れを補修



A photograph showing the base of a structure. A concrete foundation is visible, featuring a rectangular opening with a metal grate. To the right, a yellow door or panel is partially visible. The ground in front is a light-colored concrete surface. A white rectangular box with a red border is overlaid on the image, containing Japanese text.

基礎の縦割れを補修





電気メーター部、ガラスを補修







鉄部をバンジエイド補修





基礎の縦割れを補修





基礎の縦割れを補修





軒天の浮きをビス留め



TVが見れるようにアンテナ調整

